

Bearing Trees for Sections 9 & 16

| | | |
|---|----------------------------|----------------------|
| B | R. Oak 18 N 23° E 29 links | } Original not found |
| | do 18 N 10 W 63 " | |
| a | Crab Apple 6 N 30° E 24 " | } Original decayed |
| | R. Oak 9 N 81° E 59 " | |
| b | Hickory 10 the corner | |
| c | W. Oak 20 S 44° W 15 links | |
| d | B. Oak 16 S 37° W 34 " | |
| e | B. Oak 6 N 48° W 18 " | |
| f | R. Oak 13 S 12° E 27 " | |
| g | Chest 8 S 83° W 103 " | |
| H | W. Oak 20 S 36° W 51 links | } Original cut down |
| | do 10 N 13° W 45 " | |
| i | W. Oak 36 N 16° W 43 links | |
| j | B. Oak 6 N 33° W 25 " | |
| k | B. Oak 13 S 62° E 30 " | |
| l | do 16 N 85° W 30 " | |

Surveyed Sections 9 & 16 for Rezin Moore and
 Others by Mutual agreement
 The Original Bearing Trees at the N. E. corner of Sec 16
 were not to be found, the corner was made by tracing
 up the old lines from established corners —
 Surveyed April 1851

Jackson Silcott & Co. S. W. C.