

S88°42'33"E 1318.79' + 1.21' = 1320.00'

I.P.(S)

I.P.(F) N.W. CORNER
W 1/2 SE 1/4 S23
T8N, R8W

118149

RECD: June 21ST, 1979

AT 3:46 O'CLOCK P.M.

RECORDED: June 22, 1979

HOLMES CO. Plat VOL. 8 PG. 441

FEE: \$ 2.40

Richard M. Weaver Jr. RECORDER


16x7 1/2 x 2

Deed Vol. 206, Pg. 246 & 248

42.898 AC.

No. Ohio Title
ent.

1540.77'



I.P.(F)
30.00'
I.P.(S)
30.00'
I.P.(F)

N80°8'46"E
370.04'

I.P.(S)

T.R. 36

N77°33'26"E 470.81'

MAP OFFICE COPY

I.P.(S)

N79°01'6"E I.P.(S)

275.72'

N68°35'26"E
162.30'

N43°3'56"E 195.20'

I.P.(S)

T.R. 37

T.R. 36
I.P.(S)

51°56'42"W 2645.74' S88°3'18"E 1033.11'

37.316 AC.

S.W. 1/4 S23, T8N, R8W
N1°57'56"E 1046.06'

1511.86'


I.P.(F)
S.W. CORNER W 1/2 SE 1/4 S23, T8N, R8W

Hol. Co.

I.P.(S)

N88°45'14"W 1320.97'

Cost. Co.



GRAPHIC SCALE IN FEET

PLAT OF A SURVEY FOR
JOSEPH DITTA

(Grantor)

W 1/2 S.E. 1/4 S23, T8N, R8W
of Killbuck TWP, Hol. Co., Ohio

Robert L. Kasner, P.S. 5193, P.E. 28820

8/1/78