

N.W. cor'r Lot 38, 1st Q't'r.,
T.9N., R.7W., of Hardy Twp., 1045.00' E.C.R. 349

541.05'

I.P. set (1985)

Hol. Co., Ohio
PLAT OF A SURVEY FOR
HIPPLUMBER CO.
(Grantor)

S88°06'04"E 1,586.05'

Concrete Rental & Supply
V. 231 P. 745

330.52'

Known as part of Lot 38,
1st Q't'r., T.9N., R.7W., of
Hardy Twp., Hol. Co., Ohio

P.K. set inc. C.R. 349 (1985)

I.P. set (1985)

N85°16'00"W

36.99' + 563.01'

I.P. set (1985)

N26°02'23"E

1,427.9 AC.

Part of V. 183 P. 268 Tract III


100.12'

107.34'

I.P. Pin set

23.21' + 620.75'

I. Pin set



S85°16'00"E 643.96'

Hipp Lumber Co.
V. 183 P. 268

(1.4279 Ac.)

Robert L. Kasner
P.S. 5193
P.E. 28820
6122188

Chord in
C.R. 349

N28°08'00"E

8.1547 AC.

Part of V. 183 P. 268 Tract III

283.76'

This plat not approved for any use
that generates wastewater.

Hipp Lumber Co.

P.K. Nail set

N17°15'20"E

243.97'

Chord in C.R. 349

162574



M. 95.65.15

429.37'

Sanitarian

SPLIT
APPROVED
890006

MAP OFFICE COPY



Rec'd. JAN 23 1989

AT 3:26 O'CLOCK PM

Recorded JAN 24 1989

Holmes Co. Ohio Fees \$5.00

Plat Vol. 12

Pg. 138 Recorder Richard M. Green Sam

Deed Vol. 242 Page 73

I. Pin set

22.15'

P.K. Nail set

N88°33'00"W 833.24'

50' Wide strip retained by Grantor.

I. Pin set