

The following notes and remarks apply to sections 20 & 21 on the opposite page

The original corners of sec 21 are all lost except the N-W corner A one bearing yet standing

Of Sec. 21

Station	Bearing	Tree	Distance	Remarks
A	R. Oak	20	N 15 $\frac{1}{2}$ E	40 links } One of the original standing
	B. Oak	18	N 64 W	33 " }
B	R. Oak	10	S 77 W	53 links } Original could not be found
	Cherry	7	N 65 W	30 " }
C	Cherry	15	N 85 W	44 links } Original gone
	Pin. Oak	4	S 74 E	36 " }
D	W. Oak	10	N 72 E	37 links } Original gone
a	B. Oak	18	S 13 W	50 links
	W. Oak	4	S 68 E	33
b	W. Oak	12	S 61 E	22
	W. Oak	20	North	4
c	Stone	10	"	"
d	Stone	4	Planted in the Road, on large line	

The remaining corners of sections 21 - together with the ones above described - stones were planted but no bearings taken

Bearings and distances of sec. lines

C to B N 1 $\frac{1}{2}$ E 81.22 S C to D N 89 $\frac{1}{2}$ W 80.54
 D to A N 47 $\frac{1}{2}$ E 81.22 S A to B S 89 $\frac{1}{2}$ E 80.00

Of Sec 20 Bearing and distance

G to F N 89 $\frac{1}{2}$ W 80.19 S F to A S 50 $\frac{1}{2}$ W 79.84
 E to G S 89 $\frac{1}{2}$ E 80.09 S F to a S 1 $\frac{1}{2}$ W 79.80
 From e to H 39.88 S H to g 40.20
 f to H 40.00 S H to a 39.80

Bearing Trees

At G a Stone planted original, standing but decayed
 At f original not found, Sugar 16 N 83 E 50 S R. Oak 4 N 3 $\frac{1}{2}$ W 16
 Cherry 5 North 41 S Hickory 9 S 80 W 42 links
 e. W. Oak 4 South 5 S B. Oak 4 N 27 $\frac{1}{2}$ W 16
 H. Center corner } B. Oak 8 N 27 W 17 S B. Oak 8 S 66 E 12
 Sec 21 Surveyed April 1848 Sec 20 Dec 1848

J. Silcott