

Witness Pins to the corners of sections 4, 5 & 6
on the opposite page.

Map of Section 6 Surveyed Nov. 1849.

- Q. W. Oak 4 N 42 E 23 & W. Oak 20 S 40 1/4 E 75
20. Hick 15 N 74 E 27 & B. Ash 12 S 41 W 20
c. Original trees both standing } do not agree exactly
13. Cherry 15 N 85 E 56
C. W. Oak 22 N 70 W 37 } Originals decaying —
K. No Timber near
i. B. Oak 8 N 48 1/2 E 6
II. Chest 8 S 21 1/2 W 43 & So 8 N 87 W 103
h. Hickory 20 N 22 W 23
H. Chest 4 S 73 W 18 & W. Oak 4 S 18 W 25
G. Hickory 10 S 28 W 338 links
f. Chest 15 S 26 1/4 E 39
F. Chest 22 N 71 1/2 E 19 & B. Oak 6 S 66 1/2 W 30
e. no Timber near
19. W. Oak 22 N 89 E 40 Links
21. W. Oak 20 N 49 E 16 "
18. W. Oak 15 N 56 W 45 "
S6 No Timber near
17. W. Oak 20 S 65 W 44
16. Hickory 7 N 54 W 22 & W 5 S 12 W 15
15. W. Oak 15 N 41 1/2 W 17
14. W. Oak 12 N 45 1/2 E 53

Notes of Section 5

Surveyed March 5th 1850

- A. Original trees both standing and good
a. do do do do
B. Gum 23 S 76 W 29 & So 12 S 22 E 55
5. Beech 10 S 29 W 30
b. Beech 12 N 25 E 33 & So 12 S 55 W 25
12. No Timber near
4. Gum 6 S 88 1/2 E 25 & Chest 24 S 33 1/2 E 46
1. W. Oak 9 N 40 E 15 & So 20 S 92 E 31
E. (Center) W. Oak 22 N 66 1/2 E 88 & B. Oak 18 N 81 1/2 W 58
6. No Timber near
7. do do
2. B. Oak 18 N 62 E 33
3. W. Oak 18 S 72 W 13