

SURVEY REFERENCES USED


1. Subject and adjoining deeds as noted

ANITA HALL, COUNTY RECORDER

02/02/2016 11:39 AM PLAT LARGE . 86.40

ORV 255 Pg 1192

Survey maps and plats as noted



B: 2 P: 551 FILED FOR RECORD IN • denotes iron pipe found as noted HOLMES COUNTY, OH

denotes railroad spike found as

■ denotes square iron bolt found as

⊗ denotes steel axle found as noted

GRAPHIC SCALE

15 30

• denotes 5/8" diameter x 30" long rebar with "McSTEEN CA 96-026" ID cap set

MAP OF SURVEY

727 NASHVILLE ROAD

Known as being part of the Northwest Quarter of Section 1 and the Northeast Quarter of Section 2, Township 8, Range 9, now situated in the

> VILLAGE OF GLENMONT TOWNSHIP OF RICHLAND COUNTY OF HOLMES - STATE OF OHIO


Mc Steen & Associates

ENGINEERS & SURVEYORS 1415 East 286th Street Wickliffe, OH 44092 440.585.9800 Fax 440.585.9802 www.mcsteen.com

This survey is a boundary survey prepared in accordance with Chapter 4733-37, Ohio Administrative Code. The basis of bearings for this survey is South 84°-45'-00" East as the half quarter section line of the Northwest Quarter of Section 1, as evidenced by monuments found, and is the same bearing as found in Plat Volume 14, Page 72 of Holmes County Records. Distances are given in feet and decimal parts thereof. All iron pins shown as set are 30" long 5/8" rebar with an identification cap stamped "McSTEEN CA 96-026".

> 1/06/2016 REG. PROF. SURV. No. 6943 ROBERT A. DORNER

Job No.: 15—228 Field Date: November 17, 2015



Survey Date: December 8, 2015 Latest Revision Date: