



CURVE DATA				
No.	Δ	R	T	L
11	10°03'15"	1051.56'	92.50'	184.53'
12	60°22'55"	230.70'	134.22'	243.12'
13	60°32'33"	191.37'	111.71'	202.23'
14	21°45'17"	387.18'	74.40'	147.01'
15	20°34'24"	457.32'	83.00'	164.21'
16	20°01'58"	478.42'	84.50'	167.28'
16-A	8°29'25"	478.42'	35.51'	70.89'
17	27°13'45"	268.38'	65.00'	127.54'
18	29°52'08"	166.84'	44.50'	86.98'
19	35°06'49"	365.08'	115.50'	223.72'
20	11°52'51"	449.85'	46.81'	93.28'
21	54°02'15"	123.05'	62.75'	116.05'
22	54°02'15"	73.05'	37.25'	68.90'

- LEGEND**
- IRON PIN SET
 - IRON PIN FOUND
 - ▲ RAILROAD SPIKE SET
 - STONE FOUND
 - EXISTING FENCE CORNER POST
 - ⊙ TREE
 - EXISTING BUILDINGS
 - ⊞ EXISTING OIL WELL

(SEE SHEET "B" NO. 2 FOR PARCEL "B")

111877
 RECD August 26, 1977
 AT 12:02 O'CLOCK P.M.
 RECORDED August 26, 1977
 NO. 45 CO. 26 VOL. 6 P. 144
 FEE: \$13.44
 Richard H. ...
 21x32x2

PARCELS "A", "D", AND "E"	
SURVEY FOR VIRGIL E. SHREINER HARDY TOWNSHIP HOLMES COUNTY, OHIO	DATE 12-6-76 DRAWN CWM
GRINDLE AND BENDER ARCHITECTURE - ENGINEERING SURVEYING ASHLAND, OHIO 419/324-7641	SHEET 2 OF 5

